

PAVING
CONSTRUCTION PLANS
for
JOHN KING BOULEVARD
MEDIAN IMPROVEMENT
ROCKWALL BY-PASS ADDITION LOT 2, BLOCK 2


JOHN KING BOULEVARD
ROCKWALL, TEXAS

OWNER/DEVELOPER:

STANDBRIDGE COMPANIES
3008 E. HEBRON PARKWAY,
BUILDING 300
CARROLLTON, TEXAS 75010
TEL: 214-363-1998
FAX: 214-363-1997
EMAIL: sos@standbridge-co.com
CONTACT: STACY O. STANDBRIDGE

SURVEYOR/ENGINEER

m|ma
mycoskie+mcinnis+associates
civil engineering surveying landscape architecture planning
ltpce registration number: 1-2759
200 east ohran
carrollton, texas 76010
817-469-1671
fax: 817-274-8757
www.mmatexas.com
EMAIL: jsumpster@mmatexas.com
CONTACT: JACOB SUMPTER



VICINITY MAP

NO SCALE
MAPSCO GRID: 30D-B

ISSUE DATE: MARCH, 2013
CONSTRUCTION START DATE: _____, 2013

BM NO. 1
CITY OF ROCKWALL R-19. BRASS MONUMENT AT THE
NORTHWEST CORNER OF SILVERVIEW & DIAMOND WAY, ±500'
SOUTH OF SH 276.

PUBLISHED NAVD88 ELEV: 600.69'

BM NO. 2
BOX CUT ON TOP OF THE WEST CURB LINE OF JOHN KING
BOULEVARD, ON THE SOUTH CURB RETURN OF A DRIVEWAY, 615'
SOUTH OF THE CENTERLINE OF SH 276, AND 19' NORTHEAST OF
A 5/8" CAPPED IRON ROD STAMPED "MYCOSKIE MCINNIS".

ELEV: 581.15'

SHEET INDEX

SHEET NO.	DESCRIPTION
1	COVER SHEET
2	DEMOLITION, DIMENSION CONTROL, PAVING, AND GRADING PLAN
3	CONSTRUCTION DETAILS AND NOTES


SUBMITTAL #2
MAR 21 2013
City of Rockwall Engineering Dept.

Approved
3-22-13
aw

FD yes

RESPONSIBILITY NOTE:

"ALL RESPONSIBILITY FOR ADEQUACY DESIGN REMAINS WITH THE DESIGN ENGINEER. THE CITY OF ROCKWALL, IN REVIEWING AND RELEASING PLANS FOR CONSTRUCTION, ASSUMES NO RESPONSIBILITY FOR ADEQUACY OR ACCURACY OF DESIGN."



REVISION TABLE

REV.	DATE	DESCRIP.	BY