August 28, 2019

Cari Foote, MA, LPC-S, LMFT-S 203 South Fannin Street Rockwall, TX 75087

Re: 925 North Goliad Rockwall, Texas

Subject: Post-Construction Inspection

As requested, Eric L. Davis Engineering, Inc. (ELD) has visually inspected the improvements constructed at 925 North Goliad in Rockwall. The drainage flow patterns, drainage structure, and pavement addition have been built as designed. Inspection has shown that the project was constructed to meet the city approved plans and details.

Please feel free to contact us directly if you have any questions.

Mitchell K. Lenamond, P. E.