



TREE ID NO.	TREE CALIPER SIZE	TREE TYPE COMMON NAME	CONDITION OF TREE	SAVED OR REMOVED	MITIGATION CALCULATIONS	MITIGATION REQUIRED
B200	10"	ASH	GOOD	SAVED		
B201	5"	AMERICAN ELM	GOOD	SAVED		
B202	6' M.T.	CEDAR ELM	GOOD	SAVED		
B203	39"	PECAN	GOOD	SAVED		
B204	8"	AMERICAN ELM	GOOD	SAVED		
B205	13"	MAPLE	GOOD	SAVED		
B206	11"	HACKBERRY	GOOD	SAVED		
B207	6"	CEDAR ELM	GOOD	SAVED		
B208	28"	POST OAK	GOOD	SAVED		
B209	18' M.T.	ASH	GOOD	SAVED		
B210	30"	PECAN	GOOD	SAVED		
B211	27' M.T.	PECAN	GOOD	SAVED		
B212	6"	MULBERRY	GOOD	SAVED		
B213	8"	ASH	GOOD	SAVED		
B214	28"	COTTON WOOD	GOOD	SAVED		
B215	34"	COTTON WOOD	GOOD	SAVED		
B216	6"	ASH	GOOD	SAVED		
B217	6"	ASH	GOOD	SAVED		
B218	6"	ASH	GOOD	SAVED		
B219	6"	ASH	GOOD	SAVED		
B220	6"	ASH	GOOD	SAVED		
B221	8"	ASH	GOOD	SAVED		
B222	10"	ASH	GOOD	SAVED		
B223	14"	ASH	GOOD	SAVED		
B224	10"	ASH	GOOD	SAVED		
B225	8"	ASH	GOOD	SAVED		
B226	11"	ASH	GOOD	SAVED		
B227	8"	ASH	GOOD	SAVED		
B228	6"	ASH	GOOD	SAVED		
B229	8"	ASH	GOOD	SAVED		
B230	9' M.T.	AMERICAN ELM	GOOD	SAVED		
B231	4"	AMERICAN ELM	GOOD	SAVED		
B232	5"	ASH	GOOD	SAVED		
B233	5"	AMERICAN ELM	GOOD	SAVED		
B234	5"	AMERICAN ELM	GOOD	SAVED		
B235	11"	CEDAR	GOOD	SAVED		
B236	8"	CEDAR	GOOD	SAVED		
B237	8"	CEDAR	GOOD	SAVED		


TOTAL MITIGATION REQUIRED 0 INCHES

#	Revisions:	Date:

Issued For:
CONSTRUCTION
Job No.
13129
Scale
1"=50'-0"
Drawn By:
JDS
Date
8-30-2013

North Lakeshore Drive Force Main

Rockwall Texas



Tree Survey & Mitigation Plan

Sheet Number:
TS1
of TS1 Sheets